












 InSight Condition Report

2017 FIAT 500e Hatch

3C3CFFGE6HT502904 31,530 mi | Front Wheel Drive | Electric Motor | A/T | Hard Top | Premium Synthetic
 Lane/Run 4/5 Facilitation Manheim San Francisco Bay Seller CHRYSLER CAPITAL



AUTOGRADE
4.2
 Clean

 Damages	 No Structural Damage	 No Prior Paint	 Tires	 AutoCheck with history reports Clean
 Drivable	 Starts	 No Odor	 Keys 2	 Fobs 0
				 Title? (No Data)




Announcements

- CCC/NAV/DMV\$210

High Value Options

- | | | |
|------------------------|------------------------|-------------------------|
| • Bluetooth Connection | • Heated Front Seat(s) | • Rear Parking Aid |
| • Climate Control | • Navigation System | • Satellite Radio |
| • Fog Lamps | • Premium Sound System | • Tire Pressure Monitor |


Damage Overview



None ● Yellow ● Orange ● Red Severe

● Structural Issue

Exterior (10)

Description	Condition Severity	Type	Image	Additional Info
 Front Bumper Cover	Scratch Heavy 2" to 3"	Paint and Body Requires Conventional Repair		

Description	Condition Severity	Type	Image	Additional Info
● LF Door	Dent/No Paint Dmg PDR/1	Cosmetic Conventional Paint and Body Not Required		
● LF Tire	Worn Acceptable	Miscellaneous		
● L Qtr Panel	Dent/No Paint Dmg PDR/1	Cosmetic Conventional Paint and Body Not Required		
● LR Wheel	Curb Rash 1/2" to 1"	Miscellaneous		
● R Qtr Panel	Mult Dents/No Paint Dmg PDR/2	Cosmetic Conventional Paint and Body Not Required		
● RF Door	Mult Dents/No Paint Dmg PDR/2	Cosmetic Conventional Paint and Body Not Required		
● RF Fender	Dent/No Paint Dmg 1" to 2"	Paint and Body Requires Conventional Repair		
● RF Wheel	Curb Rash 5" to 6"	Miscellaneous		
● RF Tire	Worn Acceptable	Miscellaneous		

Interior (0)

No interior damages reported

Structure (0)


No structural damages reported

Other (0)

No other damages reported

Tires & Wheels

Wheels Aluminum



Left Front	Right Front	Left Rear	Right Rear	Spare
FIRESTONE	FIRESTONE	FIRESTONE	FIRESTONE	(None)
3/32"	3/32"	4/32"	4/32"	0/32"
185/55R15.0	185/55R15.0	185/55R15.0	185/55R15.0	

- 6/32 +
- 5/32 to 4/32
- < 4/32
- N/A

History



No. of Historical Events	5
Last Reported Event Date	09/13/2018
Calculated Owners	1
Last Reported Mileage	45
Calculated Accidents	0

Title and Problem Check	✔ Vehicle checks out!
Odometer Check	✔ Vehicle checks out!
Use and Event Check	! Specific vehicle use(s) or events reported
AutoCheck Buyback Protection	✔ Qualifies

CARFAX

[View CARFAX](#)

Details

Exterior Color Grigio Cenre	Top Type Hard Top	Received Date 12/30/2019	In Service Date Not Available
<div style="border: 1px solid black; padding: 5px; display: inline-block;">PAL</div>	MSRP Not Available	Inspection Location Manheim San Francisco Bay	Org Mfg Basic Warranty *4 Years/50,000 Miles
Interior Color Black	Title State CA	Work Order 2436465	*Manheim is not responsible for voided warranties
	Title Received 01/13/2020		

Equipment

Options

- A/C
- Adjustable Steering Wheel
- AM/FM Stereo
- Auto-Dimming Rearview Mirror
- Auxiliary Audio Input
- Brake Assist
- Bucket Seats
- Cargo Shade
- Cruise Control
- Daytime Running Lights
- Driver Air Bag
- Driver Vanity Mirror
- Floor Mats
- Front Head Air Bag
- Front Side Air Bag
- Intermittent Wipers
- Keyless Entry
- Knee Air Bag
- Leather Steering Wheel
- MP3 Player
- Pass-Through Rear Seat
- Passenger Air Bag
- Passenger Air Bag Sensor
- Passenger Vanity Mirror
- Power Door Locks
- Power Mirror(s)
- Power Steering
- Power Windows
- Rear Bench Seat
- Rear Defrost
- Rear Floor Mats
- Rear Head Air Bag
- Rear Spoiler
- Security System
- Stability Control
- Steering Wheel Audio Controls
- Tire Inflator
- Traction Control
- Trip Computer
- Variable Speed Intermittent Wipers

Interior

- Odometer Operable
- Premium Synthetic

Mechanical

- 0.0L None
- ABS Brakes
- Automatic Transmission
- Electric Fuel System
- Electric Motor
- Front Wheel Drive

Keys

- Combo - 2

Manufacturer Info

Manufacturer Package Information

Options

Other

- QUICK ORDER PACKAGE 2EJ
- WHEELS: 15" X 5.5" FR & 15" X 6.5" RR ALUMINUM
- GRIGIO CENTRE
- BLACK, LEATHERETTE BUCKET SEATS

Vehicle condition reports contain representations made by the seller and subjective input based on inspector judgment, which may affect any AutoGrade score. The use of the report and any AutoGrade score is subject to the Manheim Terms and Conditions and the NAAA Generic Condition Report Position Statement.

This grade was calculated under the assumption that some repairs may be covered under manufacturer warranty.

† Damage Overview diagrams are not an exhaustive representation of vehicle damage and should be viewed in conjunction with the damage detail list on each tab.

*Process protected under U.S. Patent No. 8,230,362

VIN: 3C3CFFGE6HT502904,

Work Order: 2436465

© 2020 Manheim. All Rights Reserved

[Return to the classic CR](#)